



Hazards	cuts, lacerations, electrical
Tools/Equipment	
Employee Group(s)	Facilities Management - Carpentry

Required PPE:



**Ear
Protection**



**Eye
Protection**



**Safety
Shoes**

SAFE WORK PRACTICES

- Do not perform the procedure or operate the equipment until you have been appropriately trained and authorized to do so by your supervisor.
- Inspect required personal protective equipment (PPE) and replace if required.

PROCEDURE

1. Keep hands clear of moving parts.
2. Be sure to tighten all screws and bolts prior to use.
3. Always turn off switch before making adjustments.
4. Never leave unit running when unattended.

NOTE: All PPE, tools and equipment shall be used in accordance with provincial OH&S legislation, manufacturer's specifications, applicable standards and codes of practice.